

H13-341^{Q&As}

Huawei Certified internetwork Expert - Transmission

Pass Huawei H13-341 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/h13-341.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

Which of the following is approximately equal to 100mw?

- A. 13dBm
- B. 20dBm
- C. 15dBm
- D. 10dBm

Correct Answer: B

QUESTION 2

Which of the following monitoring boards do not support 1588v2 signal processing and transparent transmission?

- A. AST2
- B. SC2
- C. ST2
- D. SC1

Correct Answer: A

QUESTION 3

Which of the following statements about avoiding the generation of discrete trails are correct?

- A. Use the trail function for configuration.
- B. For services configured on a per-NE basis, search for trails on the NMS to ensure that the service configurations are complete and standard.
- C. A fiber cut or switching test must be performed on the trail with protection routes to ensure that the configuration is complete and standard.
- D. Guide users to learn service configuration specifications.

Correct Answer: C

QUESTION 4

Which of the following is not a precaution after board replacement?

- A. Record the settings of jumpers and DIP switches on the board.

- B. For functional units that have backups, check whether the switchover is normal.
- C. Check the indicator blinking status of the board and ensure that the board works properly.
- D. Ensure that no abnormal alarm.

Correct Answer: B

QUESTION 5

Which of the following statements about replacing the SCC board is incorrect?

- A. In the case of the 1+1 hot backup of the SCC board, replacing the control board does not affect services when the active/standby switchover is performed.
- B. After the SCC board is removed, the BD_STATUS and COMMUN_FAIL alarms are reported. After the new board goes online, these alarms need to be manually cleared.
- C. If the software version of the new SCC board is later than equipment version, clear the database of the SCC board, and then downgrade the software on the SCC board to the same version as the equipment.
- D. If the software version of the new SCC board is earlier than the equipment version, upgrade the software on the SCC board to the same version as the equipment.

Correct Answer: C

[H13-341 PDF Dumps](#)

[H13-341 VCE Dumps](#)

[H13-341 Exam Questions](#)