

HQT-4120^{Q&As}

Hitachi Vantara Qualified Professional VSP G200 to VSP G800 Storage
Installation

Pass Hitachi HQT-4120 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass2lead.com/hqt-4120.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Hitachi
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

Which component in the VSP Gx00 series provides the CFM and the cache with power In case of power outage?

- A. Backup Module
- B. Battery Module
- C. Cache Module
- D. Power Module

Correct Answer: B

QUESTION 2

What are two features of the VSP Gx00 series? (Choose two.)

Which two statements are true regarding the VSP Gx00 series? (Choose two.)

- A. All the systems support cache memory up to 2TB.
- B. All the systems support FMD, SSD, SAS and NL-SAS drives.
- C. All the systems support 8 and 16 Gb Fibre Channel CHB types.
- D. All the systems support FC and SATA drives.

Correct Answer: BC

QUESTION 3

Which function is available in Hitachi Infrastructure Director (HID)?

- A. Global Active Device setup
- B. configuration of HDLM load balancing
- C. basic provisioning of a VSP Gx00 system
- D. automated provisioning for multiple VSP Gx00 systems

Correct Answer: C

QUESTION 4

What are two prerequisites for the Initial Installation of a VSP G400? (Choose two.)

- A. The SVP must be connected to the customer network.

- B. The controllers must be assembled and cabled to the SVP.
- C. Microsoft Vista must be installed on the Maintenance PC (MPC).
- D. The microcode media (CDROM or ISO image) must be available.

Correct Answer: BD

QUESTION 5

A customer wants to change a production RAID group from RAID 5 (7D+1P) to RAID 6 (6D+2P) on a VSP G600 during normal operations. They have just unmapped the LUNs from the channel ports.

What needs to be performed next?

- A. Parity groups must be deleted.
- B. The RAID level must be changed in Storage Navigator.
- C. The RAID level in the SVP Maintenance window must be changed.
- D. The RAID 5 group must be put into DRU mode in Storage Navigator.

Correct Answer: A

[Latest HQT-4120 Dumps](#)

[HQT-4120 PDF Dumps](#)

[HQT-4120 Exam Questions](#)