![Pass2Lead Logo]

7003.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura Implementation Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass2lead.com/7003-1.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

![Pass2Lead](https://Pass2Lead.com)
QUESTION 1

A technician is planning an upgrade for a customer\\'s Communication Server (CS) 1000E Release 6.0 system to Release 7x.

Which two features are now to the Release 7x Deployment manager? (Choose two)

A. Pre-configuration Remote Installation

B. Auto-select servers to which applications can be deployed

C. One-Touch System Upgrade

D. Auto-Select of the correct application file

Correct Answer: AC

QUESTION 2

A customer has installed a Media gateway controller (MGC) and would like to change the baud rate settings for the SDI parts. The baud rates for all serial Data Interface (SDI) ports on the MGC are configurable through call server?

Which overlay is used to configure the MGC SDI ports?

A. LD 137

B. LD 117

C. LD 97

D. LD 17

Correct Answer: D

QUESTION 3

Click the Exhibit button.

Managing EM on co-res-cppm(172.16.100.30)
Search for Phone

Search For Phones

Criteria: Designation ▾ Value: sales

Phones Found (11)

	Add	Import	Retrieve	Delete	<More Actions> ▾	
☐	Customer	TN ▲		Prime D	<More Actions>	Phone Type
1 ☑	0	024 0 03 00		2050	Swap	M3903
2 ☑	0	028 0 00 03		2100	Move	1140
3 ☐	0	028 0 00 04		2130	Edit	1140
4 ☐	0	028 0 00 05		2163	Save As Template	1140
5 ☐	0	028 0 00 06		2090	Logout	1140
					Sales	
6 ☐	0	028 0 00 07		2084	Sales	1140
7 ☐	0	028 0 00 08		2499	Sales	1140
8 ☐	0	028 0 00 09		2016	Sales	1140
9 ☐	0	028 0 00 10		2055	Sales	1140
10 ☐	0	028 0 00 11		2001	Sales	1140

A customer has deployed a Communication Server (CS) 1000Rls. 7x system at their site, and has asked that a swap using the Element Manager Phones tool on the two telephone sets shows in the Print-out be performed.

What should the customer be told regarding the request?

A. These two telephones cannot be swapped because they do not have competitive TN types.

B. These two telephones can be swapped because they are both assigned to TGAR 1.

C. These two telephones can be swapped because they both have the same VCE Class of service.

D. These two telephones cannot be swapped because they are not in the same Call Pickup group.

Correct Answer: A

QUESTION 4

A customer with an existing Option 11C Rls. 5.5 chassis system plans to upgrade to a Communication Server (CS) 1000E Rls. 7x Standard Availability with a single IP Media Gateway (MG) 1000E chassis.

![Pass2Lead](https://Pass2Lead.com)
To complete the upgrade, which component in the Option 11C must be replaced?

A. SSC Card

B. Call Processor

C. Media Gateway

D. Digital Line Card

Correct Answer: A

QUESTION 5

A Communication Server (CS) 1000E Rls. 7x customer has decided to implement UNIStim security with DTLS.

Which statement regarding UNIStim security with DTLS is true?

A. It is provided by the Secure Multimedia Controller 2450.

B. It encrypts UNIStim signaling between the line Terminal Proxy Server and IP telephones.

C. It provides media security between the IP telephones.

D. It provides security between the Ip telephone and Call Server.

Correct Answer: B

[7003.1 PDF Dumps](#)   [7003.1 Practice Test](#)   [7003.1 Braindumps](#)