

HP2-T25^{Q&As}

Servicing HP Rack-Tower Server Solutions

Pass HP HP2-T25 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4lead.com/HP2-T25.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



QUESTION 1

A customer has an HP Integrity rx2800 i2 server with one processor and two memory risers, each with four DIMMs. The customer added an additional memory riser with four memory DIMMs, but cannot see the additional memory at the

operating system level. The customer already swapped the first memory riser with the new one, but there is no change.

What could cause this issue?

- A. One of the new DIMMs is faulty.
- B. The new memory riser is faulty.
- C. An additional license is needed for using more than two memory risers.
- D. An additional processor is needed for using more than two memory risers.

Correct Answer: C

*The DIMMs are partitioned by the number of processors installed in the server. If you have only one processor installed in the system, you can only use 12 of the 24 memory slots. *


Table 10 Memory Load Order

	2 Processor system	n (socket 0 and 1)	1 Processor	system (socket 0)
Pair number	Memory expansion board	Memory slots	Memory expansion board	Memory slot
1	Memory expansion board 1	3A and 4A	Memory expansion board 1	3A and 4A
2	Memory expansion board 3	3A and 4A	Memory expansion board 2	3A and 4A
3	Memory expansion board 2	3A and 4A	Memory expansion board 1	1B and 6B
4	Memory expansion board 4	3A and 4A	Memory expansion board 2	1B and 6B
5	Memory expansion board 1	1B and 6B	Memory expansion board 1	2C and 5C
6	Memory expansion board 3	1B and 6B	Memory expansion board 2	2C and 5C
7	Memory expansion board 2	1B and 6B	-	-
8	Memory expansion board 4	1B and 6B	-	
9	Memory expansion board 1	2C and 5C	-	-
10	Memory expansion board 3	2C and 5C		<u></u>

QUESTION 2

Match the correct UPS description with each picture.

Hot Area:



R7000	
RP36000/:	3
R8000/3	
R/T2200 0	52
R1500 G3	
R5500	
T1000 G3	

R7000 RP36000/3 R8000/3

R/T2200 G2 R1500 G3




R7000	
RP36000/3	
R8000/3	
R/T2200 G2	
R1500 G3	
R5500	
T1000 G3	



R7000	
RP36000/3	
R8000/3	
R/T2200 G2	
R1500 G3	
R5500	
T1000 G3	



Hot Area:



R7000	
RP36000/3	3
R8000/3	
R/T2200 G	2
R1500 G3	1
R5500	A
T1000 G3	



R/T2200 (R 1500 G3	
R5500	
T1000 G3	

R7000 RP36000/3



R7000	
RP36000	1/3
R8000/3	No-
R/T2200	G2
R1500 G	3
R5500	
T1000 G	3



R7000	
RP36000/3	
R8000/3	
R/T2200 G2	
R1500 G3	
R5500	
T1000 G3	



Correct Answer:



R7000	
RP36000/3	
R8000/3	
R/T2200 G2	2
R1500 G3	
R5500	
T1000 G3	



6500 1000 G3	-	200 G2 0 G3
1000 G3	650	0
	100	0 G3

R7000



R7000	
RP36000/3	
R8000/3	
R/T2200 G2	Š.
R1500 G3	
R5500	
T1000 G3	



R7000	- 0
RP36000/3	
R8000/3	
R/T2200 G2	
R1500 G3	
R5500	
T1000 G3	

VCE & PDF Pass4Lead.com

https://www.pass4lead.com/HP2-T25.html

2022 Latest pass4lead HP2-T25 PDF and VCE dumps Download

QUESTION 3

While the system is online and the OS is operating, the HP Insight Diagnostics Diagnose feature performs diagnostics testing on which devices?

- A. network interface cards only
- B. memory and processors only
- C. hard drives attached to an HP Smart array Controller and power supplies considered diagnosable
- D. memory, processors, and network interface cards

Correct Answer: C

Using the Diagnose tab

While the system is online and the OS is operating, the HP Insight Diagnostics Diagnose feature performs diagnostics testing on the following devices:

Hard drives attached to an HP Smart Array Controller

Power supplies that are deemed diagnosable

QUESTION 4

What does adding the battery or flash backed cache upgrade NOT enable?

- A. RAID 60 migration
- B. array expansion
- C. logical drive extension
- D. stripe size migration

Correct Answer: C

Note:

* Error checking and correcting (ECC) DRAM technology protects the data while it is in cache. Smart Array battery-backed or flash-backed cache backup mechanisms protect the cache data against a server crash and power loss.

QUESTION 5



https://www.pass4lead.com/HP2-T25.html

2022 Latest pass4lead HP2-T25 PDF and VCE dumps Download

Which statement is correct?

- A. The mandatory CSR guideline applies to customers who upgrade their warranty support to carepack or contract maintenance.
- B. The mandatory CSR guideline does not apply to customers who upgrade their warranty support to carepack or contract maintenance.
- C. Mandatory and optional CSR guidelines only apply to a product with a warranty service level agreement.
- D. The optional CSR guideline does not apply to customers who upgrade their warranty support to carepack or contract maintenance.

Correct Answer: B

Currently, HP identifies two types of Customer Self Repair parts - \\'Mandatory\\' and \\'Optional\\'. \\'Mandatory\\' requires standard warranty customers to perform part replacement or pay for HP service. Self repair is optional for customers with an HP Care Pack or support agreement. \\'Optional\\' allows the customer to perform part replacement or have HP service personnel perform it at no additional charge during the product warranty period.

HP2-T25 PDF Dumps

HP2-T25 VCE Dumps

HP2-T25 Braindumps



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.pass4lead.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4lead, All Rights Reserved.