

648-238^{Q&As}

Implementing Cisco Connected Physical Security 1 Exam

Pass Cisco 648-238 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4lead.com/648-238.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers




https://www.pass4lead.com/648-238.html 2022 Latest pass4lead 648-238 PDF and VCE dumps Download

QUESTION 1


You just developed a virtual, co-located Cisco VSM 7 OVA image and added a 1 TB virtual disk for media storage. You are trying to add a Media Server via Cisco VSOM and get the following error message: "The following error occurred while verifying the hardware. Operation failed. there are no media partitions on the media server...."

Please the actions in column A below in the correct order to fix this error.

Select and Place:



Correct Answer:



QUESTION 2



https://www.pass4lead.com/648-238.html 2022 Latest pass4lead 648-238 PDF and VCE dumps Download

What is the maximum number of internal encoder ports supported by the CPS-MSP-2RU-K9?
A. 16
B. 24
C. 32
D. 48
Correct Answer: D
QUESTION 3
What is the advantage of using multicast instead of unicast to transport the camera video stream in the Cisco Video Surveillance solution?
A. When the video stream is viewed on multiple operator workstations, the network is taxed only with single multicast stream.
B. Multicast configuration on switching and routing infrastructure is less complex than the configuration for unicast traffic.
C. You can configure one camera to stream to two media servers at the same time, for data redundancy purposes.
D. Multicast is not supported in the Cisco Video Surveillance solution.
Correct Answer: C
QUESTION 4
What does it mean when the video from a camera is black and white, but otherwise the picture is clear?
A. The IR cut filter is in place
B. The camera is not streaming the color data
C. The camera has switched to night mode
D. The camera is not getting enough power
Correct Answer: C

QUESTION 5


Drag the actions from the left onto the location on the right where they are performed.

Select and Place:




https://www.pass4lead.com/648-238.html

2022 Latest pass4lead 648-238 PDF and VCE dumps Download



Correct Answer:



648-238 Practice Test

648-238 Study Guide

648-238 Braindumps



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.pass4lead.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4lead, All Rights Reserved.