

AX0-100^{Q&As}

Axis Network Video Exam

Pass Axis Communications AX0-100 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass2lead.com/ax0-100.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Axis

Communications Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

Which statements on Group of video (GOV) length are true? (Choose two)

- A. The GOV length can be adjusted in both Motion JPEG and H.264
- B. The GOV length setting only has an impact on MPEG-4
- C. The GOV length setting is only used for recording
- D. The GOV length setting has an impact on bandwidth
- E. A long GOV length increases the storage time on SD card

Correct Answer: DE

QUESTION 2

In a network surveillance installation, the purpose of a switch is to

- A. Forward the video stream between networks.
- B. Forward the video stream to the correct receiver within a network.
- C. Disconnect malfunctioning cameras from the network.
- D. Disconnect devices with invalid IP addresses from the network.

Correct Answer: B

QUESTION 3

When initiating a surveillance project with a customer, which of the following should be considered first?

- A. Understand which camera models to use
- B. Understand the customer\\'s technical knowledge
- C. Understand the customer\\'s goals and requirements
- D. Understand the legal aspects for the installation

Correct Answer: C

QUESTION 4

A convenience store needs a camera to cover the entrance. Identification is needed at 80 pixels per face. Given that the scene is 2 m (6 ft 7 in) wide, which of these resolutions is the minimum one needed?



https://www.pass2lead.com/ax0-100.html

2024 Latest pass2lead AX0-100 PDF and VCE dumps Download

Α.	640X480	
Α.	64UX48U	

B. 800 X 600

C. 1280 X 720

D. 1920 X 1080

Correct Answer: C

QUESTION 5

If image clarity changes are made within the camera web interface, but are not reflected within a Video Management Software (VMS), what is the most likely cause of the camera not accepting the settings?

- A. The camera is faulty and needs to be replaced
- B. The VMS is overwriting the changes in the camera
- C. The camera\\'s advanced settings need to be changed first
- D. The user does not have administrative rights to change the settings

Correct Answer: B

AX0-100 VCE Dumps

AX0-100 Study Guide

AX0-100 Braindumps