

E20-390^{Q&As}

VNX Solutions Specialist Exam for Implementation Engineers

Pass EMC E20-390 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass2lead.com/e20-390.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



QUESTION 1

On a VNX Data Mover, what determines a network route based on the smallest hop count between the source and the
destination?

- A. RIP
- B. NAT
- C. TCP
- D. RPC

Correct Answer: A

QUESTION 2

In which directory are VNX audit logs located?

- A. /celerra/audit
- B. /var/log
- C. /nas/var/log
- D. /nas/log

Correct Answer: A

Explanation:



Audit Backups

- Audit configuration current log file backup
 - To backend /nas/var/auditing/
 - Each Control Station synched every 180 seconds
 - >> /nas/var/auditing/cs0/ & /nas/var/auditing/cs1/
 - If Control Station in slot 0 is replaced, recovery code will restore the audit configuration files
 - >> Slot 1 auditing configuration is restored manually
 - Audit logs located in /celerra/audit

Is /nas/var/auditing/
cs0 lost+found
[root@ VNX1cs0 nasadmin]# Is /nas/var/auditing/cs0
auditd.conf audit.log audit.rules

QUESTION 3

In an environment where VNX shares are mainly used by a Web Application Server, the administrator notices very high CPU load on the Antivirus servers used by CAVA. What could be the reason?

- A. TMP files are not excluded from scan
- B. LOG files are being scanned
- C. XML files are not excluded from scan
- D. There is just one CAVA agent running on the server

Correct Answer: A

QUESTION 4

An administrator tries to modify the quota settings on a CIFS share from a Windows Server 2003 host, but the Quota tab does not exist in the network drive properties. What could be a possible cause?

- A. Quotas can be managed only with Windows Server 2008
- B. The user does not have administrator privileges on this share
- C. Exporting is implemented at the file system subdirectory level on VNX OE for File.



https://www.pass2lead.com/e20-390.html

2024 Latest pass2lead E20-390 PDF and VCE dumps Download

D. Windows users cannot modify the quota settings

Correct Answer: C

Explanation:

There is a limitation in exporting a subdirectory and setting a quota on a file system from Windows

2000/2003/08. You will not see a quotas tab when exporting at the subdirectory level.

QUESTION 5

In a VNX array with FAST VP enabled, what is the size of the data slice (chunk) that can be relocated between tiers?

A. 1 GB

B. 2 GB

C. 5 GB

D. 10 GB

Correct Answer: A

Explanation: For example, if you have Flash (SSD) disks, SAS disks, and NL-SAS disks in the pool, the Flash disks form a tier, the SAS disks form a tier, and the NL-SAS disks form a tier. Based on your input or internally computed usage statistics, portions of LUNs (1GB slices) can be moved between tiers to maintain a service level close to the highest performing storage tier in the pool, even when some portion of the pool consists of lower performing (less expensive) disks. The tiers from highest to lowest are Flash, SAS, and NL-SAS. FAST is not supported for RAID groups because all the disks in a RAID group, unlike in a pool, must be of the same type (all Flash, all FC, or all SATA). The lowest performing disks in a RAID group determine a RAID group\\'s overall performance.

E20-390 PDF Dumps

E20-390 Practice Test

E20-390 Braindumps