

H35-211^{Q&As}

HCIP-Access V2.5

Pass Huawei H35-211 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass2lead.com/h35-211.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.pass2lead.com/h35-211.html

2024 Latest pass2lead H35-211 PDF and VCE dumps Download

QUESTION 1

(multiple) Users can access the network normally, but the network speed is very slow, and the user\\'s opening rate is not reached. What are the possible reasons for the failure?

- A. User PC problem
- B. The line activation rate between the ONU and the user does not meet the requirements.
- C. The service port has a speed limit
- D. Insufficient upstream port bandwidth

Correct Answer: ABCD

QUESTION 2

(multiple) What remote acceptance functions can the MA5680T provide?

- A. PPPOE simulation test
- B. BHCP simulation test
- C. Voice call simulation test
- D. BTV simulation test

Correct Answer: ABCD

QUESTION 3

Single) When configuring multicast services on the MA5600T/MA5680T, the multicast VLAN program is statically configured. Which of the following options can be configured or not?

- A. service-port
- B. igmp user
- C. igmp program
- D. igmp profile

Correct Answer: D

QUESTION 4

(single) The correct installation method is the prerequisite for ensuring the normal operation of the ONU. Which of the following is the wrong installation method?



https://www.pass2lead.com/h35-211.html

2024 Latest pass2lead H35-211 PDF and VCE dumps Download

- A. Connect the ground wire to the ground bar
- B. Casing protection should be used at the customer line stripping
- C. When the fiber is not in use, it should be covered with a fiber dust cap.
- D. Signal lines and power lines should be placed in a centralized manner

Correct Answer: D

QUESTION 5

(Radio) The following options, regarding the description of the H.248 connection model, are correct?

- A. The connection model cannot be modified during a user session
- B. When the session between the two users ends, the corresponding association is used
- C. A media gateway that supports only point-to-point connections can allow three or more endpoints to exist in the --association at the same time
- D. When the user call is successful, the empty connection starts to be created

Correct Answer: B

H35-211 PDF Dumps

H35-211 VCE Dumps

H35-211 Practice Test